
CITY OF BALTIMORE WET W SMOKE AND DYED W	Page 1 of 3	
Sewershed: JONES FALLS	Company: REI/DRAYCO	Date: 07/16/2008
Test to be Performed: SMOKE	Ground Condition: DRY	Supervisor: ER
Manhole ID: S31UU_008MH	Test ID: 0994-379	Notifications Made:_X (Residents, Fire, 311)

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM							Page 2 of 3		
Sewershed: JONES FALLS			Company: REI/DRAYCO				Date: 07/16/2008		
Test to be Performed:			Ground Condition:				Supervisor:E.R Notifications Made:X		
Smoke:X Dyed Water:			Dry: _X Damp: Wet:						
SmokeA Byed Water			DiyX Damp wet						
Manhole ID: S31UU_008MH			Test ID: 0994-379				(Residents, Fire, 311)		
	Sketch: (Showons, Street Nam							_	
<u> </u>			Source Drainage						
No.	Address			Туре	Location	Sector	Area	Severity	Photo Number
1	242 W. 29TH ST.		03	02	01	10	03	379_OB01-01	
		•					_		
		OBSERVATION CODES							
	Source Type	Location	Sector	Severity	711011	Source	Location		
	Course Type	Location	Ocoloi	Coverity		Type	Location		
01	Main Sewer	Paved Concrete	Public	No Smoke	10	MH Frame S	Non-Paved		
	Service Line	Paved Asphalt	Private	Trace			Field/Woods		
	Cleanout	Paved Other		Moderate		Catch Basin			
	Downspout	Driveway		Major		Storm Manh			
	Area Drain	Sidewalk		,		Storm Ditch	Other		
	Driveway Drain	Curb				Excavation			
	Stairwell Drain	Yard- Front				Other			
	Foundation Drain	Yard-Back							
	Building Interior	Yard- Side							

PAGE 3 OF 3

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY JONES FALLS SEWERSHED

BALTIMORE CITY PROJECT 994 REI/DRAYCO

Unique Test ID: 379 Date: 07/16/2008 Basin: JF-19

Defect No: OB01-01 Supervisor: E.R. Dye Test Recommended: N

Address: 242 W. 29TH ST.

Source Type: 03 Location: 02 Severity: 03

Sector: 01 Drainage Area: 10

Comments: CLEAN OUT - NO CAP - MIDDLE OF PARKING LOT OF POLICE DEPT BUILDING

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 0994-379_OB01-01.jpg